



blackwood associates, inc.
architects-planners-visualization

FIELD REPORT**PAGE 1 OF 1**

OWNER X ARCHITECT X OTHER _____
CONTRACTOR _____ FIELD _____

PROJECT: SteppingStones Recreation Center**FIELD REPORT NO.:** 1**CONTRACTOR:** Flint Construction Co., Inc.**ARCHITECTS' PROJECT NO.:** 0492100**DATE:** 07/14/2004**WEATHER:** Sunny / Cloudy**TEMP:** 83°**EST. % OF COMPLETION:** N/A**CONFORMANCE WITH SCHEDULE (±):** N/A

PRESENT AT SITE: Kenton Blackwood
Pam Wean
2 workers (Laurita)

OBSERVATIONS:

Photos taken.

Vibrating roller "sealing" the soil to better shed storm water. (No sign of pumping action observed during rolling.)

Crane with steel/concrete weight dynamically compacting soil. Several drops at same place then moves to area immediately adjacent.

Trenches at front and between other buildings. Numerous large to small stones have been removed.

Worker indicated many stones have "floated" to the top during compaction work.

REPORT BY: Kenton Blackwood

611 east park avenue – fairmont, wv 26554 phone 304-366-1580 – fax 304-366-1537

e-mail: kenton@wvarchitects.com

<http://www.wvarchitects.com>